

Fort Meade Fire Department

MVC at Annapolis and Camp Meade Rds.

2 March 1974



Engine 1 1966 American LaFrance Pioneer 8C1371 before the accident.



Right side of fire truck where automobile struck the unit.



Fire truck spun 360 degrees before striking utility pole after impact with automobile.



American LaFrance pumper came to rest against the utility pole.



Right side of fire truck at pump panel.



Automobile that struck the Fort Meade pumper.

Accident photographs from the U.S. Army.